

Electrical Safety Recall

Braemar outdoor air conditioner unit models SCHF21C3S & SCHF25C3S



Batch number

Braemar by SEELEY		MODEL				
VOLTAGE	380-415 V	PRE-CHARGED R-410A			7.85 kg	
PHASE	3~ /N	LIQUID CONNECTION			12.7 mmφ	
FREQUENCY	50 Hz	GAS CONNECTION			22.2 mmφ	
RATE CURRENT	12.60 A	NET WEIGHT			148 kg	
IP CODE	IPX4	SOUND PRESSURE LEVEL			<67 dBA	
MAXIMUM PERMISSIBLE PRESSURE		GAS/LIQUID PRESSURE	COOLING	HEATING		
Pmax 4200 kPa		ADD-ON COIL	880/2650 kPa	-		
		DUCTED	860/2570 kPa	600/2290 kPa		
TEMP. CONDITION: T1 (INDOOR 27/19 °C, OUTDOOR 35/24 °C), H1 (INDOOR 20/-°C, OUTDOOR 7/6 °C)						
INDOOR UNIT	COOLING	HEATING	COOLING	HEATING	CHARGE @ 12m	ADJUST CHARGE (g)
ADD-ON COIL	21.0	-	5.99	-	7.85	
DUCTED	21.0	21.0	6.73	6.32	7.95	100
CHECK THE PRE-CHARGE AMOUNT AND ADD OR REMOVE ADDITIONAL CHARGE ACCORDING TO THIS LABEL						
SERIAL NO.		AIR CONDITIONER		MADE IN THAILAND		
SCHF21C3S 1610027AKC				N837		

IDENTIFICATION: The models SCHF21C3S and SCHF25C3S with the following batch numbers 16HxxxxAKC, (where xxxx can be numbers from 0001 – 0010 and 0017-0032). 16LxxxxAKC, (where xxxx can be numbers from 0001 – 0016 and 0033-0057). Were sold nationally by various distributors between 14 October 2016 until 28 March 2018.

DEFECT:

The power factor correction capacitors fitted in the affected batches may fail unsafely.

HAZARD:

Risk of fire in the outdoor unit.

ACTION REQUIRED:

- Stop using the air conditioner immediately, and contact Seeley International by telephone on 08 8328 3844, or by sending an email to productupgrade@seeleyinternational.com to arrange for a service technician to attend and replace the faulty capacitors.

CONTACT DETAILS:

For further information, please contact Seeley International by telephone on 08 8328 3844, or by email to productupgrade@seeleyinternational.com

See www.productsafety.gov.au
or Australian Product Recall Information